

Tread pattern depth detection report

Detection time: 2024-11-30 09:19:36

device: TTM2024

address:

phone:

email:

License plate number:

Model year: 2016

Brand: Skoda

Model: Octavia



1 Tread pattern parameter


● Normal: Depth ≥ 2.5 mm ● Warning: 2.5 mm > Depth ≥ 1.6 mm ● Danger: Depth < 1.6mm



2 Braking distance



3 Tire wear



4 Maintenance suggestions

